

BEST AVAILABLE COPY




FIG. 1

SCANNED # 4

FIG. 2A



PUT INTO TRACK
APPLY SOLVENT

FIG. 2B




FIG. 2C





FIG. 2D



PUT INTO BALANCE AND
WEIGHT OBTAIN WEIGHT W1
BAKE, REMOVE SOLVENT

FIG. 2E

